

## Vehicle Labor and Part History

<<<<<<< Ford's Automotive Serv

ADMIN 8/21/2014

Customer: Joe Martinez

Vehicle: 67 FORD MUSTANG

Phone: 714-552-7626

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
44106	12/05/1997	110,593		12/08/1997			Total: 282.64
Labor Services and Associated Parts.							
LABOR: Parts Sold							0.00
FELVS13049C	Valve cover gasket set				1.00		23.02
STDSS581	Relay				1.00		19.15
AE	Battery corrosion protect				2.00		1.00
SV	Cleaning solvent				1.00		0.32
GS	Gasket sealer / adhesive				1.00		0.35
456-135221	Rock arm adjuster screw				1.00		9.65
LABOR: Computer scope engine: > ___cylinder power, relative compression test. ___Ignition system, wires, dist, rotor, timing advance ck. ___Co & hc readings hi & low speed. ___Charging, alternator___voltage___amps engine seems to be rough running adjust dwell and timing							1.00 60.00
LABOR: Am running or starting inspect & adjust carburetor [ ] choke linkage/fast idle [ ] adjust pull off if needed [ ] clean accumulation of foreign deposits. [ ] Egr [ ] ign timing [ ] advance am1 hard to get started adjust							0.00
LABOR: Remove valve covers as needed to determine why engine is making valve train clicking noise replace broken rocker adjuster screw adjust all valves							2.00 120.00
LABOR: Charging system test complete alternator/voltage regulator, starter [ ] battery water [ ] cable condition [ ] tray & holdown: [ ] load test battery to 9.6 volts: note amps___ [ ] alternator out put volts ___ amps ___ avr [ ] test for electrical shorts: draws ? ___ replace starter solenoid and repair bad connections at starter and battery							0.75 45.00
40030	9/24/1996	109,707		9/26/1996			Total: 1,923.21
Labor Services and Associated Parts.							
LABOR: Parts Sold							0.00
HAY2710	Fan clutch				1.00		61.30
FELHS8554PT	Cylinder head gasket set				1.00		105.45
HYG224D	Carburetor overhaul kit				1.00		39.38
CSC	Spray cleaner				1.00		3.05
GS	Gasket sealer / adhesive				1.00		0.35
ST	Shop towel				4.00		0.72
SV	Cleaning solvent				1.00		0.32
JB	J.B. Oil additive engine				1.00		5.95
32	Anti-freeze				3.00		27.75
OIL15	10/30 quaker state engine				5.00		9.75
ACPF2	Oil filter--a/c delco				1.00		9.56
45	Resistor sparkplug				8.00		25.20
SHC	Hose clamp-small				4.00		5.00
LHC	Hose clamp-large				2.00		3.10
BDXD11	Brake pad set--organic				1.00		39.88
BDX66845	Caliper overhaul kit				2.00		52.48
BF	Brake fluid				5.00		5.00
AL	Caliper / brake lubricant				1.00		0.85
ANTI	Brake anti squeek materia				1.00		0.50
BSC	Brake cleaner				1.00		3.25
VS692	Valve spring				4.00		20.28
V2463	Exhaust valve				6.00		75.00

# Vehicle Labor and Part History

<<<<<<< Ford's Automotive Serv

ADMIN 8/21/2014

Customer: Joe Martinez  
Vehicle: 67 FORD MUSTANG  
Phone: 714-552-7626

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
SHO30110	Valve seat					8.00	78.56
SHO7011	Valve guide					16.00	35.68
SHOA503	Valve spring shim					16.00	8.96
STDVC31	Vacuum advance					1.00	22.80
LABOR: Computer scope engine: > ___cylinder power, relative compression test. ___Ignition system, wires, dist, rotor, timing advance ck. ___Co & hc readings hi & low speed. ___Charging, alternator___voltage___amps replace vacuum advance that had a ruptured diaphragm. Reset base ignition timing.						1.10	55.00
LABOR: Check cooling system for leaks or overheating. ___Over heating or leaks: cooling system check out. > ___Pressure test system for 15-20 minutes. ___Ck. Water pump bearing: û ___Weep hole for leaking. ___Visual look at freeze plugs ___û clearance on belts/hoses ___hoses:___belts:___radiator condition. Cs1 remove and replace fan clutch note: fan shroud is missing.						0.50	27.00
LABOR: Courtesy brake inspection: > remove all 4 wheels ___visual examination of brake system. 30_% of lining remaining rear vacuum booster is weak							0.00
LABOR: Remove both cylinder heads for inspection / repair clean all associated parts reset timing change oil and filter						12.00	474.96
LABOR: *carburetor overhaul : 4 barrel carb: cb4 remove carburetor from vehicle, disassemble, clean, install carb kit, reinstall on vehicle, make idle and mixture adjustments.						3.50	185.01
LABOR: Reline front disc brakes : overhaul front calipers br05 > replace disc pads/repack wheel bearings/true brake rotors						1.78	98.99
LABOR: Valve grind v-8 cylinder heads							0.00
LABOR: Remove and replace all valve guides in cylinder heads							0.00
LABOR: Remove and replace all exhaust seats in cylinder heads							0.00
LABOR: Resurface both cylinder heads							0.00
30709	4/27/1993	88,817		4/27/1993		Total:	438.98
Labor Services and Associated Parts.							
LABOR: Parts Sold							0.00
32	Anti-freeze					2.00	21.90
12F	Freon					1.75	26.69
AW1075-01	Water pump					1.00	88.22
18495-0TR	Heater valve					1.00	44.70
FS-84515-01	Fitting					1.00	24.20
LABOR: Check heater. Check engine temp.							0.00
LABOR: Repairs on speedo: only used parts were available. No guaranty on trip.							0.00
LABOR: Replace water pump and inspect bypass.						1.90	104.99
LABOR: Install new heater fitting and heater valve.						0.50	25.00
LABOR: Replace heater core no/charge						2.25	0.00

Vehicle history for the past 500 months.

## Vehicle Labor and Part History

<<<<<<< Ford's Automotive Serv

ADMIN 8/21/2014

Customer: Joe Martinez

Vehicle: 67 FORD MUSTANG

Phone: 714-552-7626

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
LABOR: Remove speedo for repairs and reinstall.						0.25	12.50
30116	2/12/1993	86,836		2/12/1993		Total:	0.00
Labor Services and Associated Parts.							
LABOR: Parts Sold							0.00
999HC	Heater core				1.00		
TG	Water outlet gasket						
S347180	Thermostat				1.00		
FEL35004	Thermostat gasket				1.00		
LABOR: Check coolant leak inside car pressure check and advise remove and replace heater core that was defective. ***Core was blown out at the seams***						6.10	0.00
LABOR: Check and see why drivers inside door handle will not open door. Will need car back another time to repair door.							0.00
LABOR: Warranty repair							0.00
29970	1/21/1993	86,250		1/21/1993		Total:	0.00
Labor Services and Associated Parts.							
LABOR: Parts Sold							0.00
999	Rebuilt starter--warranty				1.00		
LABOR: Check starter grinding remove starter and inspect as required replace starter under warranty						0.90	0.00
29666	12/17/1992	85,121		12/18/1992		Total:	1,257.54
Labor Services and Associated Parts.							
LABOR: Parts Sold							0.00
2211-CR	Heater core				1.00		65.82
32	Anti-freeze				2.00		21.90
OS-30764-0CM	Oil pan gasket set				1.00		18.71
JV-707-P	Rear main set kit				1.00		27.95
SEK	Transmission seal kit				1.00		74.50
OILATF	Transmission fluid						
FS84740-01	Fitting				1.00		6.12
OIL15	15/40 multi-grade engine				5.00		9.75
FRAPH8A	Oil filter				1.00		9.85
D	Drain plug kit				1.00		2.75
12F	Freon				2.00		21.90
SHC	Hose clamp-small				2.00		2.50
LABOR: Steam clean engine and under car.							0.00
LABOR: Replace leaking heater core. Pressure test system when finished.						5.20	285.01
LABOR: Radiator repair & rod-out. Sublet cs5							0.00
LABOR: *notice: radiators in extremely poor condition may not be > able to be repaired & may require a new radiator core.							0.00

## Vehicle Labor and Part History

<<<<<<< Ford's Automotive Serv

ADMIN 8/21/2014

Customer: Joe Martinez

Vehicle: 67 FORD MUSTANG

Phone: 714-552-7626

RO #	Date	Mileage	Service Writer	Date Paid	Flat Rate Hrs	Billed Hrs / Part Qty	Extension
						1.00	55.00
						4.00	248.00
						0.90	50.00
							0.00